ACCURACY


refers to how close
measured values
are to the actual
(accepted) value

PRECISION

refers to how close
measured values
are to each other