# Significant Figures

### Digits 1-9

## Always Significant


#### Leading Zeros

Never Significant

#### Captive Zeros

## Always Significant

## Trailing Sometimes Zeros Significant



Multiply & ( Divide Round the product or quotient so that it has the same number of significant figures as the measurement with the fewest significant figures.

#### Rules for Rounding >5 Round Up Round to an Even Number =5 < 5 Round Down